

CERTIFIED LAND CORNER RESTORATION

32-9


Index No. B-5

State of Wisconsin }
County of Langlade } ss.

I Raymond S. Hallisy, do hereby certify that on the 15th day of July, 1972, I found evidence of the N 1/4 corner of Section 5 and 6 Township 32, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

Corner Set by Ripco Paper Co

Description of corner evidence found:

1" pipe with 2" Aluminum Cap

Description of monument and accessories I established to perpetuate the original location of this corner.

Corner sets 1/4 mile South of CTH "J" on McCloud Road
East side in East-West fence
corner marked
No trees nearby.



Dated at Antigo, Wis., this 15th day of July, 1972.

Signature Raymond S. Hallisy Title Reg Land Surveyor Registration No. 500685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy