

CERTIFIED LAND CORNER RESTORATION

Index No. J-3

State of Wisconsin }
County of LANGLADE } ss.

I WILLIAM F. KELLY, do hereby certify that on the 3RD day of DEC., 19 81, I found evidence of the S. 1/4 corner of SEC. 7 Township 32, North, Range 9 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

EMIL FOLTA


History of original corner establishment:

ORIGINAL CORNER ESTABLISHED BY HIRAM C. FELLOWS IN SEPT., 1860.



RES. WITNESS IDENTIFIED LOCATION OF AXLE AS CORNER.

Description of corner evidence found:

3" AXLE BURIED 1" DEEP, FOUND IN PLACE.
SET 2, 1 1/2" x 42" BLACK IRON PIPES WITH BRASS CAP WITNESS MONUMENTS.



Description of monument and accessories I established to perpetuate the original location of this corner.



○ = Corner monument restored.

Dated at ELCHO, Wis., this 3RD day of DEC., 19 81.

Signature William F. Kelly Title COUNTY SURVEYOR Registration No. 1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy