

CERTIFIED LAND CORNER RESTORATION

32-9  
Index No. J-9

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

Corner Set by Ripco Paper Co.

I, Raymond S. Hallisy, do hereby certify that on the 26<sup>th</sup> day of August, 1972, I found evidence of the Section corner of 8, 9, 17, 16 Township 32, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Two 1 1/2" pipes with 3" square brass caps with 1" solid pipes along side. Set 50 links North and South of Lloyd Creek road

Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.


BT To North witness corner  
12" spruce N57E 24.7 FT.  
BT To South witness corner  
8" spruce S12W 4.2 FT

CAPS MARKED

CORNER MARKS  
NORTH  
58/59  
S17/516  
T32N R9E  
RIPCO

CORNER MARKS  
SOUTH  
58/59  
S17/516  
T32N R9E  
RIPCO

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 26<sup>th</sup> day of August, 1972

Signature Raymond S. Hallisy Title Registered Surveyor Registration No. 5-00685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy