]	F	2	•	3	5	5]	i	C	1	E		I	1	t
	-		•			1/4								
-	-	-	-		-						-			-
		-						-	-					

County of LANGLADE

location of this corner.

witnesses:

I WILLIAM F. KELLY , do hereby certify that on the 4th day of Dec. , 19.8/ , I found evidence of the CENTER corner of SECTION B

9 EAST Fourth Principal Meridian,

as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

SECTION 8

O = Corner monument restored.

\cap	F	RT	IF	IFD	IAND	CORNER	RESTORATION	
U	ᆮ	пπ	15	ロロロ	LAND	CORINER	RESTURATION	

Index No. G - 7


State of Wisconsin History of original corner establishment: SS.

> ORIGINAL CORNER ESTABLISHED BY HIRAM C. FELLOWS IN SEPT., 1860.

Description of corner evidence found:

Dated at.....

1/4" IRON PLATE SET IN IRON PIPE, FOUND IN PLACE, AS WITNESS MONUMENT. SET 14 / RON PIPE AS CORNER.



Description of monument and accessories I established to perpetuate the original location of this corner.

D & 7 H	BT PK NAIL SET /N CROSS	PINE TO BE SET NAIL TO SET IN IRON PLATE SET NAIL TO SET IN IRON PLATE SET IN IRON PLATE SET IN IRON PLATE SET I'M' I.P.	732N, R9E C1/4 58 CORNER 40 LINKS WEST	
NORTH	THE NAIL SET IN CROSS		RIPCO	
Dated at	ELCHO	, Wis., this 4th day of day of	DECEMBER	, 19.8/

Signature Wulliam 5. Kelly Title County Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official	Registration No/098
Office of Register of Deeds, County of	, I hereby certify that the within, 19

(Register of Deeds)