CEDTICIED	LAND	CODNED	RESTORATION	10
CERTIFIED	LAND	CURINER	RESTURATION	JIN

Index No. J-15

State of Wisconsin

County of LANGLADE

Ss. History of original corner establishment:

I. WILLIAM F. KELLY , do hereby certify that on the 4th day

Township........, North, Range

as described hereon; and that from this evidence I established a new monument and accessories

as described hereon to perpetuate the original

T32N, R9E

location of this corner.

Resident witnesses:

evidence of the 5. 1/4 corner of SEC. 10

Dec. , 19 81 , I found


9 EAST , Fourth Principal Meridian,

ORIGINAL CORNER ESTABLISHED BY HIRAM C. FELLOWS IN SEPT., 1860.

Description of corner evidence found:

14" IRON PIPE, FOUND IN PLACE.
ESTABLISHED 2 WITNESS TREES.

SET A 2" * 42" BLACK RON PIPE WITH BRASS CAP WITNESS MONUMENT.



Description of monument and accessories I established to perpetuate the original location of this corner.

1	0LD 87			/	IIT. COR.
NORTH	RESCRIBED PK NAIL SET/N CROSS	IZ" MAPLE NEW BT SET NAIL ONLY	2" BRASS CAP W	5 % Sec T32	R. 25' SOUTH 4 CORNER CT + 10 2N - R9E 2 - 4 - 81
Dated a	it ELCHO	, Wis., this	4世 day of	DEC.	, 19.81
Signatu	re William F. Ru (County Surveyor, Re	Title	COUNTY SURVE	YOR Registra	tion No. /098
instrum	f Register of Deeds, County ent was filed in this office for o'clock	ofr record on the	day of	, I hereby cert	ify that the within, 19
••••••	(Register of	Deeds)	·		

O = Corner monument restored.