


CERTIFIED LAND CORNER RESTORATION

Index No. G-17

State of Wisconsin }
 County of LANGLADE } ss.


I WILLIAM F. KELLY, do hereby certify that on the 9th day of SEPTEMBER, 1977, I found evidence of the corner of _____ Township _____, North, Range _____, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



○ = Corner monument restored.


History of original corner establishment:



William F. Kelly 9-9-77


Description of corner evidence found:

LOCATED WELL POINT AND BEARING TREE FROM SURVEY RECORDS OF M. HUTCHINSON.



Description of monument and accessories I established to perpetuate the original location of this corner.

SET 4\"/>



Dated at ELCHO, Wis., this 9th day of SEPTEMBER, 1977

Signature William F. Kelly Title REGISTERED LAND SURVEYOR Registration No. 51098
 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE