

CERTIFIED LAND CORNER RESTORATION

Index No. N-11

State of Wisconsin }
County of LANGLADE } ss.

I WILLIAM F. KELLY, do hereby certify that on the 29th day of MAY, 1981, I found evidence of the NORTH 1/4 corner of SECTION 21 Township 32, North, Range 9 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:

ORIGINAL CORNER ESTABLISHED
BY HIRAM C. FELLOWS IN SEPT., 1860


Description of corner evidence found:

LOCATED EXISTING AXLE
BY PAROLE EVIDENCE.




William F. Kelly

Description of monument and accessories I established to perpetuate the original location of this corner.



SET 1 1/2" BLACK IRON
PIPE BRASS CAP
WITNESS MONUMENTS



1 1/2" BRASS CAP
WIT. MON.
WIT COR
COR 33' (E/W)
N 1/4 COR
SECT. + 21
T32N, R9E
5-29-81
W F K

Dated at ELCHO, Wis., this 2ND day of JUNE, 1981.

Signature William F. Kelly Title COUNTY SURVEYOR Registration No. 1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of, I hereby certify that the within instrument was filed in this office for record on the day of, 19..... at o'clock M.

(Register of Deeds)

By Deputy

○ = Corner monument restored.

FORM 985 H. C. MILLER CO., MILWAUKEE