	CERTIFIED LAND CORNER RESTORATION	Index No. 44-5
State of Wisconsin ss.	History of original corner establishment:	31-9
County of Langlade	Corner originally set by James Marsh in May, 1851.	15CONS
I William F. Kelly , do hereby certify that on the 31st day	Corner was reset by D. A. Hintz in 1937 resurvey.	WILLIAM F.
of December 1979, I found evidence of the Southwest		S1098 ♣
corner of Section 32		ELCHO, WIS.
corner of Section 32 Township 32, North, Range 9 East , Fourth Principal Meridian,		
as described hereon; and that from this evidence	Description of corner evidence found:	SURVEY
I established a new monument and accessories as described hereon to perpetuate the original location of this corner.	Found 4" iron pipe with brass cap and old bearing tree set by Hintz.	stump Willenan S. Kel
Resident witnesses:		
•		•
•••••		
	Description of monument and accessories I established to perpetuate the original location	of this corner.
1	TOZN RAE	121
T32N R9E	7" MAPLE 31/2 4" IRON PIPE 31/32	
	FOUND FOUND ST 52	
	TAIN LANG CO. 1	
	(6) - M8Z M = - Z - Jio	P.K. NAIL
	12" A5H 810	
1 1 0	NEW NEW	87:5 BLAZED AS SHOWN
Sec. 32	Dated at ELCHO , Wis, this 7 day of JAN	1980
	Signature Wellam & Jelly Title County Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)	Registration No. 1098
	Office of Register of Deeds, County of, I here instrument was filed in this office for record on the, day of	eby certify that the within
	ato'clock	, 19
	(Register of Deeds)	
<u></u>		
O = Corner monument restored.	ByDeputy	