## O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION


Index No. X - 6

History of original corner establishment:

Set corner on line between and equidistant from West ¼ corner and Center of Section 32.

Description of corner evidence found:

Found no evidence of corner being previously set.



Description of monument and accessories I established to perpetuate the original location of this corner.

| 13" MAPLE | 13" M

(Register of Deeds)

at.....o'clock...... M.