

CERTIFIED LAND CORNER RESTORATION

Index No. **A-17**
31-9

State of Wisconsin }
County of ANTIGO } ss.
I, RAYMOND J. HALLISY, do hereby
certify that on the 27 day
of SEPTEMBER, 1980, I found
evidence of the SE, SECTION
corner of SEC 34
Township 32 N, North, Range
R9E, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:
H. HALLISY
S. BARGANDER

History of original corner establishment:


1937 LANGHADE COUNTY RESURVEY

Description of corner evidence found:

CORNER MISSING
BEAR TREE WHITE PINE STUMP 36" S72°E 46.4 LINKS
RESET CORNER BY CHAINING EAST FROM 1/16 CORNER SEC
34 19.775 CHAINS AND TYING IN WITH W. PINE STUMP
BEARING TREE AND OLD HAYES ROAD.

SEE REVISED
IN 32-9


Description of monument and accessories I established to perpetuate the original location of this corner.



REESTABLISHED 2" IRON PIPE PLUS BRASS CAP

NEW BEARING TREES SCRIBED B.T.

- 1) BLACK ASH CLUMP (3 TREES) 7"-5"-7" S28°E 60.8 LINKS
- 2) DEAD ELM 8" S90W 56.0 LINKS
- 3) YELLOW BIRCH 10" N80W 51.5 LINKS
- 4) SOFT MAPLE 4" N81°E 42.4 LINKS



T31N R9E SEC 3
○ = Corner monument restored.

35 Dated at ANTIGO, Wis., this 27 day of SEPTEMBER, 1980.

Signature Raymond J. Hallisy Title Reg Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

SEC By 2 Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE 43209340000