

CERTIFIED LAND CORNER RESTORATION

Index No. A-15
31-9

State of Wisconsin }
County of LANGHADE } ss.

I, RAYMOND J HALLISY, do hereby certify that on the 27 day of SEPTEMBER, 1980, I found evidence of the SOUTH 1/4 corner of Sec 34 Township 32, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


G. Keyka Jr

History of original corner establishment:

RESURVEY MAY 22, 1937

Description of corner evidence found:

4" BRASS CAP OF 1937 - STAMPED




1937 BT
HEM 12 S74°W 39.09 LKS (MISSING)
HEM 12 N37°E 16.36 LKS (MISSING)

Description of monument and accessories I established to perpetuate the original location of this corner.

MONUMENT LEFT IN PLACE - EXCELLENT CONDITION

NEW BEARING TREES - SCRIBED B.T.

HEMLOCK 16" S40°W 49.7 LINKS
HEMLOCK 18" N90°W 23.4 LINKS
MAPLE, SOFT 7" S70°E 15.1 LINKS



T31N Sec 3 R9E
○ = Corner monument restored.

Dated at ANTIGO, Wis., this 27 day of SEPTEMBER, 1980

Signature Raymond J Hallisy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE

43209340020