

CERTIFIED LAND CORNER RESTORATION

Index No. A-23

State of Wisconsin }
County of LAWLOR } ss.

I Raymond S. Hallisy, do hereby certify that on the 19TH day of MARCH, 1988, I found evidence of the Y4 corner of 1 E 36 Township 31 E 32, North, Range 9 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

CORNER SET IN THE 1930 RESURVEY

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP



Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S

- 10" RED MAPLE N 58 E 22' 6"
- 8" RED MAPLE S 85 E 29' 6"
- 10" RED MAPLE S 7 E 4' 4"
- 8" RED MAPLE S 82 W 20' 5"


Dated at ANTIGO, Wis., this 19TH day of MARCH, 1988.

Signature Raymond S. Hallisy Title SURVEYOR Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy



○ = Corner monument restored.

FORM 985 H. C. MILLER CO., MILWAUKEE

43209360720