State of Wisconsin

0 =	Corner	monument	restored.
$\sim$	00		. Cotor ca.

## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Description of corner evidence found:

FOUND CORNER DOWN WHERE HIT BY ROAD MACH. FOUND HOLE WHERE IT HAD BEEN



32 40

William de Kelly


Description of monument and accessories I established to perpetuate the original location of this corner.

SET Z" IRON PIPE W/BRASS CAD MKD SET GUARD POST ALONG SIDE

1=	ELM	12	N30E	30.0
2=	ELM	8	พรรพ	26.5

3: BASSW, ZO S 45W 395 DLD BLAZE ON BW

ALL TREES BLAZED & SCRIBED MBT



THIRD TO ABANDON TOWN DUMP ROAD ENDS AT COR YEMINEST of DRMSBY ROAD



Dated at FICHO	, Wis., this	16TH	day of	MATC	, 19.74
Signature Milliam & Kolli (County Surveyor, Register	Title ed Land Surve	REG. LAND	Survey or authorized official)	Registration	No.5-1098
Office of Register of Deeds, County of instrument was filed in this office for recat	****************		,	I hereby certify	that the within
(Register of Deeds	s)				