History of original corner establishment:

Description of corner evidence found:

SANGLE IRONS WELDED TOGETHER WITH POINT ON END. ROTTEN WOOD IN HOLE WHERE LIRONS WERE SET. ALSO AT JON BLAZED CUTTING LINES.

KELLY \$1098 ELCHO.

32-10

William & Kelly

Description of monument and accessories I established to perpetuate the original location of this corner.

Set	2."	I	Ron	1 PIPE	ω	BRASS	CAP	MKD.
Nex	τ .	TO	4	IRON.	,	1		

(Register of Deeds)

1= Maple S=5 N46° W 19.6 Z= SPRUCE W - 8 525 W 35,1 3: Balsam 8 5376 30.0

ALL TREES BLAZED AND SCRIBED NBT

	GEC.	Ge \
1	10	11
	15	14 VRIOE
1		FK
	-	

Dated at	, Wis., this	974	day of	Wex	, 19 74
Signature William & Kelly (County Surveyor, Register)	Title	Reg. Lar	40 Surv	eyor	Registration No.S-1098
(County Surveyor, Register	d Land Survey	or, or other dul	y authorized of	fficial)	5
Office of Register of Deeds, County of					
nstrument was filed in this office for reco	rd on the		day o	of	, 19
nto'clock					

 \bigcirc = Corner monument restored.

State of Wisconsin

County of LANGLADE,

location of this corner.

Resident witnesses:

I., Wm. F. KELLY, do hereby certify that on the 9TH day

of May , 19.74 , I found

evidence of the Section

corner of SECS, 10-11-14-15 Township 32, North, Range 105 Fourth Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

C.A. MCEACHEREN

R. KOHN

SEC.10	Sec 11/	
SEC.15	Sec.14	