County of	LANGLA	ΔE			
ofocto evidence of corner of Township/O. East as described I established	the We Secr. Sa 32 Fereon; and hereon to	57 /4, 19, ourth Prince d that from	North, Range ipal Meridian, this evidence at the original		
Resident wit	nesses:				
		••••••			
		•••••			
	ナマラ A/	PIOS			
	1 3270	, <i>R 10 E</i> 1			
1		 			
			+		
		i !			
	2	19	<u>-</u>		
1		 -	1		
<u>- !</u>		 	<u> </u> 		
1	i				
○ = Corner monument restored.					

State of Wisconsin

SS.

CERTIFIED LAND CORNER RESTORATION	CERTIFIED	LAND	CORNER	RESTORATION
-----------------------------------	-----------	------	--------	-------------

Index No. T-S

History of original corner establishment:

ORIGINAL CORNER ESTABLISHED BY

HIRAM C. FELLOWS IN SER, 1860

Description of corner evidence found:

3/4" IRON BAR WITH VELLOW PLASTIC

COATING, FOUND IN PLACE.

I.B. SET BY WP.S

SURVEY OF 1974

WILLIAM F.

KELLY

S1098

ELCHO,

WIS.

SET A W2" x 42" BLACK IRON PIPE WITH BRASS CAP WIT. MONUMENT.

Description of monument and accessories I established to perpetuate the original location of this corner.

PK NAIL WIPLESTIC COREING, F.		SECT. 29
Dated at <u>Eccho</u> , Wis., th	is 2/sr day of	OCTOBER 1981
Signature Milleum J. Kelly Title (County Surveyor, Registered Land Su	e COUNTY SURVEYO	R Registration No. 1098
Office of Register of Deeds, County ofnstrument was filed in this office for record on the at		, I hereby certify that the within

(Register of Deeds)

.....Deputy