

CERTIFIED LAND CORNER RESTORATION

Index No. D-11

State of Wisconsin }
County of LANGLADE } ss.

History of original corner establishment:

I RAYMOND J. HALLISY, do hereby certify that on the 9th day of MAY, 1981, I found evidence of the ESTABLISHED SOUTH CORNER 1/16 corner of SECTION 4 Township 32, North, Range 11 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

CORNER WAS ESTABLISHED BY A TRANSET SURVEY

Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.


SET A 1 1/2" IRON PIPE WITH A BRASS CAP

BT, S

BASSWOOD 9" N 78° W 28.6'

RED MAPLE 5" N 3° E 30.5'

BLACK CHERRY 6" S 82° E 14.5'



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 9th day of MAY, 1981.

Signature Raymond J. Hallisy Title Reg. LAND SURVEYOR Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 R. C. MILLER CO., MILWAUKEE