

CERTIFIED LAND CORNER RESTORATION

Index No. C-11

State of Wisconsin }  
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby certify that on the 9<sup>th</sup> day of MAY, 1981, I found evidence of the ESTABLISHED CENTER 1/4 corner of SECTION 4 Township 32, North, Range 11 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

Description of corner evidence found:

CORNER WAS ESTABLISHED BY A TRANSIT SURVEY

Description of monument and accessories I established to perpetuate the original location of this corner.



SET 2" IRON PIPE WITH A BRASS CAP

BT,S

ASPEN 7" N72°E 15.3'

ASPEN 10" N76°W 26.9'

ASPEN 10" S31°W 18'



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 9<sup>th</sup> day of MAY, 1981.

Signature Raymond J. Hallisy Title REG. LAND SURVEYOR Registration No. 5685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy

FORM 985 R. C. MILLER CO., MILWAUKEE