	T	32 N, R	ν <i>ε</i>
		1	l
		1	1
1 1			
	!	İ	
•		9-	
	Ì.		1
	!	1	!

State of Wisconsin

WILLIAM F. KELLY

corner of SECTION 9

location of this corner.

Resident witnesses:

certify that on the day of 19.80, I found evidence of the WEST 1/4

Township........, North, Range

II EAST , Fourth Principal Meridian,

as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

County of LANGLADE

SS.

○ = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. G - 9

History of original corner establishment:


DRIGINAL CORNER SET BY HIRAM C. FELLOWS IN SEPT. 1860.

Description of corner evidence found:

NONE.

CORNER WAS ESTABLISHED BY DOUBLE PROPORTIONING BETWEEN THE NW AND SW CORNERS OF SECTION 9.

NOTE: EXISTING FENCE LINES DO NOT AGREE WITH LOCATION OF CORNER ESTABLISHED BY SURVEY



William J. Rella

2"x 42" BLACK IRON PIPE WITH BRASS CAP MONUMENT.

Description of monument and accessories	I established to perpeti	ate the original location of	this corner.
N	· -	10	2" PIPE WIT
ALL BT'S NEW	N 18. W G. 20. 2" PIPE WITH CAP	77° € 9.90°	WEST 1/4 CORNER
THERON	NAPLE MAPLE	NORWAY PINE PLANT. SEEDLINGS 1980	5 ECT. 9 T 32 N, R II E 6-2-80 WFK
Dated at ELCHO,	Wis., this 10 th	day of JUNE	, 1980
Signature Welliam J. Kelli (County Surveyor, Registered	Land Surveyor, or other du	Surveyor Reg	gistration No. 5-1098
Office of Register of Deeds, County of instrument was filed in this office for recor at			
(Register of Deeds)			
(Register of Deeds)			