

CERTIFIED LAND CORNER RESTORATION

32-11

Index No. J-13

State of Wisconsin }  
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 19th day of June, 19 71, I found evidence of the Section corner of 9, 10, 16, & 15 Township 32, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Description of corner evidence found:

Found  $1\frac{1}{4}$ " iron pipe with rock mound, blazed lines to the West, East and North.



Resident witnesses:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Description of monument and accessories I established to perpetuate the original location of this corner.

Placed 4" brass cap in the  $1\frac{1}{4}$ " iron pipe and surrounded same with 4" of cement. Placed location poster about  $2\frac{1}{2}$  chains south on a ~~X~~ 4" Elm next to Fire Lane.

BT's to corner  
12" Hard Maple S4E 5 Feet 7 inches  
14" Hard Maple N76W 1 Foot 9 inches  
BT's faced at base of tree and acribed BT



○ = Corner monument restored.

Dated at Antigo, Wis., this 19th day of June, 19 71

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

\_\_\_\_\_  
(Register of Deeds)

By \_\_\_\_\_ Deputy