

CERTIFIED LAND CORNER RESTORATION

32-11 Index No. J-15

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby
certify that on the 22nd day
of August, 1970, I found
evidence of the 1/4
corner of Section 10 & 15
Township 32, North, Range
11E, Fourth, Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

History of original corner establishment:

Set in May 1938 by M. Hutchinson

Description of corner evidence found:

Found old pipe underground, his B.O. Stone with cross
on top, N44 $\frac{1}{2}$ E 52 Links



Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap in cement monument 4" by 2 Ft.

No B.T.'s



Dated at Antigo, Wis., this 22nd day of August, 1970

Signature Raymond J. Hallisy Title REG. LAND SURVEYOR Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19____
at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.