of	t on the	1/1/19	/, do hereby day 
evidence of		- 116	2/2
Township		<u> </u>	North, Range
	12.E, F	ourth, Princ	cipal Meridian,
			this evidence and accessories
			e the original
location of	this corner.		J
Resident w	itnesses:		
	••••••		
	***************************************	***********	
	<del></del>	· · · · · · · · · · · · · · · · · · ·	
	1	1	
	1	1	1
	1	1	
	i	<u> </u>	†
	! }	1	
	ر در دی ا	1	1
	26071	12 /2 R 11E	+
	132 N	RILE	1
	1	· · · · · · · · · · · · · · · · · · ·	
	<u> </u>	!	<u>-</u> <b>-</b>
İ		! !	; T
I		İ	1
4		ļ .	1
1		1	1 1

State of Wisconsin

County of LANGINGE

O = 0	orner	monument	restored.
-------	-------	----------	-----------

CERTIFIED LAND C	ORNER F	RESTORATION
------------------	---------	-------------

History of original corner establishment:

CORNER Set in The 1930 Resurvey

Description of corner evidence found:

Found wood post down, point intact, MARKED 5/16 57 512

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with bRASS CAP.

Bt's TO CORNER ASPEN 11" N24E GFT 21N. Cherry 8" N 78W 21FT 1in. BT'S FACED AT BASE OF TREE AND SCRIPED BT

E see see	15
2 12 17 Cx 5 16 3	3

Dated at Agt 190 , Wis., this // Ta day of Jaly 1971 Signature Land Surveyor, Registered Land Surveyor, or other duly authorized official)

Registration No. 5-685 Office of Register of Deeds, County of ......, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_\_day of \_\_\_\_\_\_\_, 19\_\_\_\_\_\_ 

(Register of Deeds)