

CERTIFIED LAND CORNER RESTORATION

Index No. G-25

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:


Corner established in 1939 RESURVEY

32-11

I Raymond J. Hallisy, do hereby certify that on the 30th day of March, 1985, I found evidence of the V4 corner corner of Section 7 Township 32, North, Range 12 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4" Iron pipe with BRASS CAP in center of marsh



Resident witnesses:


.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.S

- TAM 6" S80°W 25.8 FT
- TAM 5" N62°E 35.1 FT
- TAM 8" N77°E 63.8 FT
- TAM 6" S83°E 37.5 FT

set a new squared TAM stake along side of pipe



○ = Corner monument restored.

Dated at Antigo, Wis., this 30th day of March, 1985.

Signature Raymond J. Hallisy Title land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy

FORM 985 M. C. MILLER CO., MILWAUKEE