

CERTIFIED LAND CORNER RESTORATION

32-11

Index No. M-15

State of Wisconsin }  
County of LANGLADE } ss.

History of original corner establishment:

CORNER SET IN 1938 BY M. HUTCHINSON

I RAYMOND HALLISY, do hereby certify that on the 26 day of April, 1969, I found evidence of the So. CTR. 1/16 corner of 15 Township 32N, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

IRON PIPE AND REMAINS OF A HARD MAPLE B.T. - A STUMP

Resident witnesses:

GERALD WEIX


JERRY KEYKA

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2 INCH IRON PIPE WITH BRASS CAP

MARKED  
1 32N R 11E  
SOUTH CENTER  
1/16  
SEC 15

BEARING TREES MARKED WITH "B.T."  
EM 22" S 88W 7'4"  
HARD MAPLE 14" S 88°E 22'2"



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 4 day of June, 1969

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy