	f Wisconsin	1
- 3 41.1.5	HUGHADE	} ss.
evidence of the corner of	NORTHE AND ATTHEMENT OF THE PRINT OF THE PRI	9.8.1., I found 15.7
Resident witnes	ses:	
		<u>-</u>
		•••••••••••••••••••••••••••••••••••••••
makes and	2 N R (2 E	•
Y 40°	- Land American A Street Policy	
	ı	-
	1	
1		
	12	
	12	
	12	
	12	
	12	
	12	

CERTIFIED	LAND	CORNER	RESTORATION

Index No. E - 15

History of original corner establishment:

1930's COUNTY RESURVEY PROJECT

Description of corner evidence 4" BRASS CAP AND ROCK HOON	T32 N R 12 116	e \	WHITE PINE DIONOT IC DIONOT HI	OUT OROP S45°E 67.6 KINICS 9" NB5"W 66.5 LINKS DENTIFY OLD B.T. 446 FIBLD NOTES TIME - ALSO SIDUS CO
Description of monument	and accessories I established to p	erpetuate the		All the same to the Common of
CORNER L	EFT IN PLACE	-	J	
NEW BEA	ARING TREES			
	1) HARD HAPLE 8"	569°W	33' 2"	
	2) HARD HAPLE B" :	562°E	15' 7"	
ų.	3) BASS WOOD 12" 1	N51°E	Z2' 8"	HAS OLD BLAZE
•	4) HARD MAPLE TH	NGOF	20124	
	TREES SCRIBED			
Dated at ANTIGO		/ day	of JANUAR	1981
Signature Kayulluk (County Su	Title Control of the Land Surveyor, or ot	ther duly authoric	zed official)	Registration No. 3 685
Office of Register of Deeds	, County of		. I here	by certify that the within
instrument was filed in this ato'clock	s office for record on the	d	ay of	, 19
	Register of Deeds)	••••		
Ву	Σ	Deputy		