

CERTIFIED LAND CORNER RESTORATION

Index No. **E-23**

State of Wisconsin }  
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby certify that on the 24 day of JANUARY, 1901, I found evidence of the NORTH 1/4 QUARTER corner of Sec 12 Township 32 N, North, Range 12 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....


History of original corner establishment:

1930's County Resurvey Project

Description of corner evidence found:

4" BRASS CAP

NO BEARING TREES



CORNER ON SOUTH SIDE OF GRASSY FROST POCKET

Description of monument and accessories I established to perpetuate the original location of this corner.

LEFT BRASS CAP IN PLACE

NEW BEARING TREES

- 1) ASPEN 6.5" N 15° E 53' 10"
  - 2) ASPEN 3.5" N 36° W 13' 7"
  - 3) CHERRY STUB 5" S 10° E 24' 7"
  - 4) ASPEN 7" S 59° W 61' 10"
- TREES SCRIBED B.T. ON BASE

Dated at ANTIGO, Wis., this 24 day of JANUARY, 1901

Signature Raymond J. Hallisy Title REG. LAND SURVEYOR Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)


Office of Register of Deeds, County of ....., I hereby certify that the within instrument was filed in this office for record on the ..... day of ....., 19..... at ..... o'clock ..... M.

.....  
(Register of Deeds)

By ..... Deputy

FORM 985 R. C. MILLER CO., MILWAUKEE

T32N R12E



○ = Corner monument restored.