

CERTIFIED LAND CORNER RESTORATION

Index No. C-25

State of Wisconsin }  
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby certify that on the 2ND day of APRIL, 1988, I found evidence of the Y4 corner of 1 & 6 Township 32, North, Range 12 & 13 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....  
.....  
.....

History of original corner establishment:

CORNER SET IN THE 1930 RESURVEY


Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP  
OLD BT 12" HARD MAPLE N75W 15'



Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S  
8" HARD MAPLE S87E 12' 7"  
10" HARD MAPLE S27W 26' 10"  
14" BRASS WOOD S65W 30' 6"  
12" HARD MAPLE N52W 26' 6"



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 2ND day of APRIL, 1988.

Signature Raymond J. Hallisy Title SURVEYOR Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By.....Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE