

CERTIFIED LAND CORNER RESTORATION

Index No. C-21

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 1st day of May, 1982, I found evidence of the 1/4 corner of Section 1 & 2 Township 32 12E, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:

Corner set in the 1930 resurvey.



Description of corner evidence found:

4" iron pipe with brass cap, Rock mound.

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

12"	Basswood	N45E	7.7'
10"	Hard Maple	N6E	16.1'
14"	Basswood	N70W	14.2'
12"	Hard Maple	S11W	5'



○ = Corner monument restored.

Dated at Antigo, Wis., this 1st day of May, 1982.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 R. C. MILLER CO., MILWAUKEE