

CERTIFIED LAND CORNER RESTORATION


Index No. E-21

State of Wisconsin }
County of Lafayette } ss.

I Raymond J. Hallisy, do hereby certify that on the 16th day of September, 1984, I found evidence of the Section corner of 1, 2, 11, & 12 Township T32N, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:


1930 resurvey.

Description of corner evidence found:

4" iron pipe with brass cap bent over by logging equipment, also all ~~XXXXXXX~~ BT's destroyed in logging operation.

Description of monument and accessories I established to perpetuate the original location of this corner.

Reset brass cap monument and drove a 7' plastic fence ~~XXXX~~ post alongside. No trees are nearby for BT's.



Dated at Montigo, Wis., this 16th day of September, 1984.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE