

CERTIFIED LAND CORNER RESTORATION

Index No. E-17

State of Wisconsin }
County of Langlade } ss.


I Raymond Hallisy, do hereby certify that on the 20th day of June, 1987, I found evidence of the Section corner of 2, 3, 10, 11 Township 32, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Established in 1930 RESurvey

Description of corner evidence found:

4" IRON Pipe with Brass CAP




Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT, S

12" BASSWOOD S 72 W 23.1'
8" Cherry N 48 E 6.4'
10" BASSWOOD S 80 E 38.1'
12" BASSWOOD S 16 E 46.6'



○ = Corner monument restored.

Dated at Antigo, Wis., this 20th day of June, 1987

Signature: Raymond Hallisy Title: Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy