State of Wisconsin

CERTIFIED LAND CORNER RESTORATION
History of original corner establishment:
Corner established in the 1930 resurvey.
Description of corner evidence found:

Found old squared stake down, point in ground

B.T.'s faced at XXX base of tree and scribed BT

By......Deputy

Marked W 1/16 S 4 S 9

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap

B.T's to corner

EXXX Elm 14" S46W 39Ft. 4 inches

Elm 6" N63W 32Ft. 9 inches

Dated at Antigo , Wis., this 4th day of May , 19 69.

Signature August File Reg. Land Surveyor Registration No. 5-685

Office of Register of Deeds, County of , I hereby certify that the within at o'clock . M.

(Register of Deeds)

Sec 9

O = Corner monument restored.