			t and access uate the ori
location of	this corner	•	
Resident w	itnesses:		

	1		l l
	1		1
	1		1
1	T]:[-	
	د با		
.3	ا س	الأي	Sie c
.3	€ C 5 	5. 3	\$EC
.3	# c 5 	S. 12.	14 -
.3	c 5 	S. 14.7.0	3/2 C - +
.3	Ec 5 1	C. H. 'S	Sie C
.3	C S S S S S S S S S	S. 14. 20	3/2 C - +

State of Wisconsin

I Raymond J. Hallisy , do hereby certify that on the 4th day

County of Langlade

evidence of the.....

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

32-12 Index No. G-9

History of original corner establishment:

Corner reestablished in the Resurvey in the 1930's

Description of corner evidence found:

Corner was lying next to a picket set by the Forestry Crew when the road was relocated. This picket was set 100 lks. of the true corner.


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 4 inch brass cap with cement 100 lks. west of true corner.

B.T.'s to Witness Corner:

Elm 6" N88W 57 Ft. 6 inches Elm 9" S84W 68 Ft. 3 inches

B.T.'s faced at base of tree and scribed BT



Dated at	Antigo	, Wis., this	4th	day of	May	, 19. 69
Signature	(County Surveyor, Fister of Deeds, County	Title Title Segisfered Land Surveyo	Reg. Land	Surveyor authorized official	Regist	ration No. S-6 85
ınstrument w	ister of Deeds, Count as filed in this office to clock	or record on the		day of	, I hereby ce	ertify that the withi , 19
	(Register o	f Deeds)				
Bv			Deputy			