

CERTIFIED LAND CORNER RESTORATION

Index No. C-9

32-12

State of Wisconsin }  
County of Langlade } ss.

I Raymond J. Hallis, do hereby certify that on the 15th day of April, 1928, I found evidence of the W.C. 1/4 corner of Section 4 Township 32, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


Resident witnesses:

History of original corner establishment:

Corner Established in 1939 Resurvey

Description of corner evidence found:

This monument was found tripped over by Highway Dept  
4 inch Iron Pipe with Brass cap  
OLD B.T.s  
Elm 11" S80°W 68 FT. 2 inch  
Elm 8" N88°W 57 FT. 4 inchs




Description of monument and accessories I established to perpetuate the original location of this corner:

Reset 4 inch Iron Pipe with Brasscap in original location.  
New B.T.s  
Aspen 4" S71°W 3 FT. 11 inchs

FORM 985 H. C. MILLER CO., MILWAUKEE

T 32 N R 12 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 15th day of April, 1928.

Signature Raymond J. Hallis Title Registered Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy