CERTIFIED	LAND	CORNER	RESTORA'	TION

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake standing also 3/4" pipe & 1" pipe along side. Stake marked W 1/16 S7 S18

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound. New B.T. 's Hard Maple 26.4 Ft. Hard Maple N76W 17.3 Ft.

B.T.'s faced at pase of tree and scribed BT.


(K32	NK12E
	18 416

Dated atAnd		, Wis., this.	2.	5th	day of	April	***************************************	1970
Signature MM (Con Office of Register of	ed Malles inty Surveyor, Registere	.fTitle Land Surve	Reg.	Land her duly a	Survey	o r ficial)	Registration	n No. S-685
Office of Register of instrument was filed	Deeds, County of Lin this office for reco	ord on the		Salat.	day of	, I he	ereby certify	that the within
ato'clock					Junian Citi			
	(Register of Deeds)	, , , , , , , , , , , , , , , , , , ,		; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;				
D.,			Υ.					

State of Wisconsin County of Langlade

I Raymond J. Hallisy, do hereby certify that on the 25th day of April , 19.70 , I found evidence of the W 1/16 corner of Section 7 12E , Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



O = Corner monument restored.