State of Wisconsin
County of $\frac{2AN34ADE}{}$ ss.
I. G. M. MENNA + G. W.C.X., do hereby certify that on the day of J.
Resident witnesses: Many Many Many Many Many
SEC 8 1
○ = Corner monument restored.

CEDTICIED	LAND	CODVIED	DECTODATION	,
SERTIFIED	LAND	CORNER	RESTORATION	ı

By......Deputy

32-12 Index No. J. 9

History of original corner establishment:

NOUEMBER 16, 1939

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP

Description of monument and accessories I established to perpetuate the original location of this corner.

TESET SAME 4" IRON PIPE SOFT WEST AS W.C.