
O = Corner monument restored.

CERTIFIED	LAND	CORNER	RESTORATION
CENTILED	LAND	CORNER	RESTURATION

History of original corner establishment:

SET BY KOWALKE-CIRCA 1939.



Description of corner evidence found:

FOUND 4" PIPE W BRASS CAP - FOLLOWING HUTCHINSON'S NOTES.

Description of monument and accessories I established to perpetuate the original location of this corner.

SET MOUND OF STONES AROUND MON & BLAZED & TREES.

1= MAPLE & N 38% W 30.1

2= BASSWOOD G N 88 1/2 6 16.95

3= BLACK CHERRY & SIBE 13.35

17 11-16-39

ALL TREES BLAZEDE SORIBED NBT.

Dated at , Wis., this , 11 TH	day of	July	. 1974
Signature William J. Rell Title Reg. LAND (County Surveyor, Registered Land Surveyor, or other du Office of Register of Deeds, County of	Surveyore uly authorized official)	Registration	1 No. <b>5-1098</b>
Office of Register of Deeds, County of instrument was filed in this office for record on the at		I hereby cortities	* hoak alaa
(Register of Deeds)			