CERTIFIED	LAND	CODNED	RESTORATION
	LAND	CORNER	RESTURATION

32-12

History of original corner establishment:

NEUEMBER 15, 1939 RESURVEY

Description of corner evidence found:

CEDAR STAKE

By......Deputy

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 1/2" IRON PIPE AS W.C. 50 EKS MEST

Dated at 17 15 0 , Wis., this 10 th day of 1979 , 1963 Signature Title Go Clark Registration No. (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of....., I hereby certify that the within (Register of Deeds)

O = Corner monument restored.

} ss.

State of Wisconsin

I & MEKENNA + & WEIX, do hereby

certify that on the ______ day of APRIL , 1963, I found evidence of the No 8711 116

Township.........., North, Range Fourth Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories as described hereon to perpetuate the original

County of LANGLADE

location of this corner.

Resident witnesses: