

CERTIFIED LAND CORNER RESTORATION

Index No. J-11

32-12

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 25th day of March, 1978, I found evidence of the North 1/4 corner of Section 16 Township 32, North, Range 12 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


Resident witnesses:

History of original corner establishment:

Corner Established in 1939 Resurvey

Description of corner evidence found:

4 inch IRON PIPE WITH BRASS CAP
Fence North, South, EAST & West




Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.S
Hard MAPLE 6" S56E 13 FT. 3 inches
Hard MAPLE 7" N38E 23 FT. 3 inches
Hard MAPLE 6" N58W 16 FT. 5 inches

FORM 985 H. C. MILLER CO., MILWAUKEE

T 32 N R 12 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 25th day of MARCH, 1978

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy