


U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.
 O = Corner monument restored.



North quarter corner to Section 15, T32N, R12E

- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1857 - James McBride, contract surveyor, set a wood post at this corner location and marked bearing trees for accessories.


1939 - WPA Surveyor, D. A. Hintz, found evidence of McBride's BTs and corner post and monumented same with a 3" iron pipe and brass cap

1996 - Kim Pritzlaff, RLS located Hint's iron pipe which was found in good condition on the west side of a knoll 934 feet east of Legend Lake as noted in Hintz' report. The monument was accepted and tied off as shown.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)
 Describe witness monuments.

- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

Corner consists of a 3" dia iron pipe with brass cap stamped for corner. Bearings are magnetic to trees which were blazed and scribed "BT" at the root crown. Distances are to aluminum nails in the tree crown.



DT ADDED TO LOCATION 8/2008

J15

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?


Found Perpetuated Location

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

No

(i) I, Kim H Pritzlaff, RLS No. 1259
(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.



Signature

10/96

Date

