

CERTIFIED LAND CORNER RESTORATION

Index No. J-1

32-13

State of Wisconsin }
County of Kanglade } ss.

I Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1928, I found evidence of the W.C. To Section corner of 7, 12, 13, 18 Township 32, North, Range 12 & 13 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

Corner Established in 1939 Resurvey

Description of corner evidence found:


4 inch Iron Pipe With Brass Cap



Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.S

- Cherry 10" N69°E 65 FT. 4inchs
- Cherry 8" S43°W 29 FT. 7inchs
- Cherry 9" N61°W 16 FT. 10inchs
- Light Pole N6°E 65 FT 5inchs Pole Number 32-12-12R1



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1928.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy