

CERTIFIED LAND CORNER RESTORATION

Index No. N-25

State of Wisconsin }
County of Langlade } ss.


History of original corner establishment:

Corner Established in 1939 Resurvey

I Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the W.C. to section corner of sections 13, 18, 19, 24 Township 32, North, Range 12 E 13 1st, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:


4 inch Iron Pipe With BRASS CAP



Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s
Hard MAPLE 18" 578°E 75' 4 inches
light Pole N9°E 1' 4 inches
Rock Mound



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy