

CERTIFIED LAND CORNER RESTORATION

Index No. L-25

State of Wisconsin }
County of Langlade } ss.


History of original corner establishment:

Corner Established in 1939 Resurvey

I Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the W.C. To West 1/4 corner of Section 18 Township 32, North, Range 13 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4 inch Iron Pipe with Brass Cap



Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.S

Hard Maple 14" S63°W 16' 5"


Hard Maple 9" N65°W 36' 2"

Light Pole N89°E 9' 5 1/2"

Pole Number 32-12-13E3

FORM 965 H. C. MILLER CO., MILWAUKEE

T 32 N R 13 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy