

CERTIFIED LAND CORNER RESTORATION

Index No. N-19

State of Wisconsin }
County of Lan glade } ss.

I Raymond J. Hallisy, do hereby certify that on the 10th day of April, 1982, I found evidence of the 1/4 corner of Section 14 & 23 Township 32 12E, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:

Corner set in the 1930 resurvey.



Description of corner evidence found:

4" iron pipe with brass cap.

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

6" Yellow Birch N80E 22.6'
8" Basswood N18W 12.4'
12" Ironwood S39W 18.6'



○ = Corner monument restored.

Dated at Artigo, Wis., this 10th day of April, 1982.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. 52685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE