

CERTIFIED LAND CORNER RESTORATION

Index No. E-5

State of Wisconsin }
County of Lanlade } ss.

History of original corner establishment:

I, Raymond J. Hallisy, do hereby certify that on the 5th day of Sept., 19 70, I found evidence of the Section corner of 5, 6, 7, & 8 Township 32, North, Range 13E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found old squared stake with rock mound. This corner has been used for a starting point for several surveys.

Resident witnesses:

[Signature]
[Signature]

Description of monument and accessories I established to perpetuate the original location of this corner.


Set 2" pipe with brass cap, rock mound.

New B.T.'s


Hard Maple 8" N2W 11 Ft. 7 inches

Hard Maple 4" S52W 20 Ft. 10 inches

B.T.'s faced at base of tree and scribed BT



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo Wis., this 5th day of Sept., 19 70.

Signature [Signature] Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of [Signature], I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy