

CERTIFIED LAND CORNER RESTORATION

32-13

Index No. **E-3**

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy do hereby certify that on the 12th day of June, 1971, I found evidence of the 4 corner of Section 6 & 7 Township 32, North, Range 13, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

History of original corner establishment:

Corner set in about 1957 by Langlade county Forestry Dept. & WCD

Description of corner evidence found:

Found squared wood stake and rock mound.

BT's

10" Hard Maple **EX** S45E 2 Feet 11 inches
14" Hard Maple N52E 42 Feet


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.


BT's to corner (New)

6" Hard Maple S76W 6 Feet
5" Hard Maple N60E 11 Feet

BT's faced at base of tree and scribed BT



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 12th day of ~~XXXX~~ June, 19 71

Signature R. J. Hallisy Title Reg. Land Surveyor Registration No. 1685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy