

CERTIFIED LAND CORNER RESTORATION

32-13

Index No. E-2

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallsy do hereby certify that on the 12th day of June, 1971, I found evidence of the W 1/16 corner of Section 6 & 7 Township 32, North, Range 13E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

History of original corner establishment:

Corner set in about 1957 by Langlade county Forestry Dept. & WCD.


Description of corner evidence found:

Found wood stake down
BT's
14" Elm N43W 24 Feet 11 inches
12" Hard Maple S16E 40 Feet 10 inches


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

BT's to corner (New)
5" Elm N67E 6 Feet 1 inch
11" Basswood S8W 5 Feet 8 inches
BT's faced at base of ~~the~~ and scribed BT



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 12th day of June, 1971

Signature R. J. Hallsy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)
By _____ Deputy