

CERTIFIED LAND CORNER RESTORATION

Index No. B-5

State of Wisconsin }  
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 5th day of Sept., 1970, I found evidence of the N. 1/16 corner of Section 6 Township 32, North, Range 13E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

J. Weis

J. Kupa

History of original corner establishment:

Corner set in 1950 by W.C.D and Langlade County Forestry Dept. in the survey of the east line of Section 6

*Filed*

Description of corner evidence found:

Found Squared oak stake

Description of monument and accessories I established to perpetuate the original location of this corner.


Set 2" pipe with brass cap, rock mound.

New B.T.'s

White Pine 20" N10W 19 Ft. 2 inches

Elm 10" S18E 19 Ft. 2 inches

B.T.'s faced at base of tree and scribed BT.



○ = Corner monument restored.

Dated at Antigo, Wis., this 5th day of Sept., 1970.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy