State	e of Wisc	consin]
County of.	LANGL	ADE	} SS.
certify that of	t on the	24, 19	, do hereby day ZS, I found North, Range pal Meridian, this evidence day accessories the original
Resident w	itnesses		
resident w	ithesses.		
***************************************		***************************************	
•••••		•••••	


	732N	R13E	1
	 	i 	
		[
	;		
	!!!!	 	
	!/_ !	3	
		T	Ψ
		1	
	! !!	!	
,	1	1	
!	1	1	
		1	
O = Corner	monument	restored.	

CERTIFIED LAND CORNER RESTORATION	CER"	TIFIED	LAND	CORNER	RESTORATIO	N
-----------------------------------	------	--------	------	--------	------------	---

(Register of Deeds)

Index No.ムースケ

History of original corner establishment:



Description of corner evidence found:

EAST 1/4 CORNER ESTABLISHED BY EXTENDING THE BEARING & DISTANCE BETWEEN THE FOUND EAST 18 COR., OF THE SE14, SEC. 13, & THE SE CORNER OF SECTION 13.

Description of monument and accessories I established to perpetuate the original location of this corner.

Q /2 CEDER N
RISE RIGE 13 + 18 T 32-N 11-24-78 N.F.K 12"CEPER 12"CEPER N. P. P. S. N. P. S
Dated at ELCHO, Wis., this 7 day of DECEMBER, 1978
Signature Mulliam d. Welly Title COUNTY SURVEYOR Registration No.5-1098 (County Surveyor, Registered Land Surveyor, or other duly authorized official)
Office of Register of Deeds, County of
instrument was filed in this office for record on theday of
ato'clock