

CERTIFIED LAND CORNER RESTORATION


Index No. P-23

State of Wisconsin }
County of Langlade } ss.

I Raymond Hallisy, do hereby certify that on the 3rd day of August, 1974, I found evidence of the Center 1/4 corner of Section 24 Township 32, North, Range 13 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

Description of corner evidence found:

1 1/2" pipe blazed line West and South


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap

BT's

5" Hard Maple N 53 E 5 FT 10 inches

6" Basswood N 12 E 11 FT 6 inches



Dated at Antigo, Wis., this 3rd day of August, 1974

Signature Raymond Hallisy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy