

CERTIFIED LAND CORNER RESTORATION

32-13

Index No. V-25  
V25

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

Original survey 1859  
Resurvey 1914

I, Raymond J. Hallisy, do hereby certify that on the 29th day of June, 1968, I found evidence of the Witness Corner - NE Sec. Cor. corner of Sec 36 Township 32 N, North, Range 13 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found wood post and rock mound. Also a location tag dating 1937

Resident witnesses:


J. Weix G. Kryka  
\_\_\_\_\_  
\_\_\_\_\_

Description of monument and accessories I established to perpetuate the original location of this corner.


Set Witness Corner: Standard Brass Cap in cement with rock mound  
BT'S to witness corner: 12 Hard Maple S 24° W 35' 10"  
12" White Ash N 63° W 13' 6"

Brass Cap marked as:

The section corner is located 100 ft. north and 60 ft. east of the Witness Cor. in the center of the R.R. tracks.



BT  
12" ASH  
O W.C.  
BT  
12" MAPLE



○ = Corner monument restored.

Dated at Antigo, Wis., this 31 day of August, 1968

Signature Raymond J. Hallisy Reg. Land Surveyor Registration No. 685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy