LANGLADE COUNTY
U.S. PUBLIC LAND CORNER RESTORATION

The East Quarter corner of Section 26, T. 32 N., R. 13 E., Langlade County, WI.

Corner was: (check all that apply) 4321326 2000 2014

- ☐ Restored through acceptance of an obliterated evidence location.
- ☒ Restored through acceptance of a found perpetuated location.
- ☐ Determined to be lost and re-established through proportionate methods.
  Show bearings and distances to PLSS corners used for proportioning, and show original distances).
- ☐ Restored/recovered/re-established in a location that differs from a previously established position.
  (Show difference in plan view below).
- ☐ Check here if addition information is shown on the reverse side of this form.

Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.

The original corner was established in 1857 by Alfred Millard. Original bearing trees: hemlock, N75°E, 4 links and a sugar, 12", S28°E, 4 links. There is no evidence in the records to indicate that this corner was ever used or maintained after the original government survey, however, I believe that Owens-Illinois surveyed in the area. On 07/17/2012, Dale Carlson and I found a wood post on the ground. After a bit of searching, we found the point of the wood post in the ground, pretty rotten. There appears to be an old blazed and painted line running both to the North and South from here. Traversed to the north for a distance check, which is fine. Accepted the location of the point of the wood post as the accepted location of the quarter corner. Set the monument described below and marked bearing trees as shown.

Physical description of the monument set:

Set a 2" x 36" pointed aluminum pipe with aluminum cap, about flush with ground.
Set a steel channel post with "Forest Boudary" sign, 0.6' north of corner monument.

Describe the accessories used to perpetuate the corner. Include a plan view drawing and accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would aid in future recovery of the corner.





11/19/2014

I, David E. Tlusty, Registered Land Surveyor, as Langlade County Surveyor, certify that the corner location on this record was determined by me and that this U.S. Public Land Survey Monument Record is correct to the best of my knowledge and belief.



O = corner perpetuated

The East Quarter corner of Section 26, T. 32 N., R. 13 E., Langlade County, WI

Index No. T21 32-13